[2021] No.008 | Release Note

Date: Sep 26th, 2021

Subject: i73 Firmware v2.2.1.3

Region: International

1. Introduction

The improvements and modifies described in this note are made since version 2.1.7.2 to the following CHC i73 GNSS receivers:

I73   PN: A10675430005050005

With this release, all above receivers can use version 2.2.1.3 firmware.

2. Version2.2.1.3 Release Note

The release note describes the new features, improvements and bug fixes for the Firmware v2.2.1.3.

Issue	Description	Type
GGA output	When GGA output is 5, the display of i73 changed from fix to float	BUG Fixes
Language	The web page can support Spanish switching.	Improvement
Bluetooth	Solved the problem that Broadcom Bluetooth may not start	BUG Fixes

3. Installing the new Firmware

The new firmware can be download at: https://chcnavigation.jianguoyun.com/p/DRQL01YQutyuBhiQs5cE

4. Additional Information

For more information about this change, please contact support@chcnav.com

For any further information, please contact support@chcnav.com

CHCNAV Technical Support

CC to Report: Xunye Mao/Henry Gu/Francois Martin
CC to: Sales team/Support team/Order team/Marcom team